



TEL : ( 503 ) 2375 – 2290  
2375 – 2348  
2375 – 2425  
2375 – 2440

AFS: MSLPYOYX

E-Mail: [oficiales.ais@cepa.gob.sv](mailto:oficiales.ais@cepa.gob.sv)

REPUBLIC OF EL SALVADOR  
COMISION EJECUTIVA PORTUARIA AUTONOMA  
EL SALVADOR INTERNATIONAL AIRPORT  
SAN OSCAR ARNULFO ROMERO Y GALDAMEZ  
AERONAUTICAL INFORMATION SERVICE

**AIC**  
**Series A**

01/24  
08 JAN

---

## Temporary Prohibited Flights of Boeing 737 MAX 9 Airplanes in Salvadoran Airspace

The Civil Aviation Authority of El Salvador (AAC), in accordance and compliance with the provisions of Article 7 paragraph 4 of the Organic Law of Civil Aviation, notifies all personnel involved that:

Flying El Salvador airspace is prohibited to The Boeing Company Model 737 MAX 9 airplanes.

This AIC derives as a result of the Emergency Airworthiness Directive (AD) 2024-02-51 issued by the FAA.

The AAC has considered appropriate to take this measure in favor of the safety of our airspace and our passengers. The B737 MAX 9 airplanes, certified in any category, with a mid cabin door PLUG installed, will be able to operate in El Salvador until the airplanes comply with the inspections and all applicable corrective actions have been performed.

Once the inspections and all applicable corrective actions have been performed, the operator must show evidence of compliance with the emergency AD 2024-02-51. Additionally, the operator must submit the evidence to its Principal Maintenance Inspector (PMI) of the AAC so that the B737 MAX 9 airplanes can be scheduled to operate in Salvadoran airspace.

This AIC will become effective upon its date of publication, and it is of mandatory compliance.

For further information about this AIC, contact Miguel Chorro, Manager, Airworthiness, AAC; phone 503-2565-4423, email: [mchorro@aac.gob.sv](mailto:mchorro@aac.gob.sv)