



TEL : (503) 2375 – 2290
2375 – 2348
2375 – 2425
2375 – 2440

AFS: MSLPYOYX

E-Mail: oficiales.ais@cepa.gob.sv

REPUBLIC OF EL SALVADOR
COMISIÓN EJECUTIVA PORTUARIA AUTÓNOMA
EL SALVADOR INTERNATIONAL AIRPORT
SAN ÓSCAR ARNULFO ROMERO Y GALDÁMEZ
AERONAUTICAL INFORMATION SERVICE

AIC
Series A

11/23
19 SEP

Modification of aircraft taxi guide line to the north apron (aircraft stands 1, 2, and 3).

From 10:00 a.m. local time on the 21st to 5:00 p.m. on September 29, 2023, for maintenance work on the foxtrot taxiway, provisional guidance lines must be used for aircraft entering or leaving the north apron. (Positions 1, 2 and 3 of the international ramp), as a mitigation measure, a guidance service for aircraft on the ground (Follow Me Truck) will be implemented.

Air traffic controller (surface) will notify the pilot that his entry or exit from the north platform will use a guide vehicle (Follow Me Truck) and he must follow the line that the vehicle will be indicating. The ramp officer on board the guide vehicle, having the aircraft in sight, will begin the movement at a speed of no more than 30 kilometers per hour. Upon reaching the points of the old guide line, the guide vehicle will move towards the Perimeter Street or service street to free the taxiing of the aircraft.

Note: if the pilot does not follow the provisionally drawn guide line, the ramp officer on board the vehicle will signal to stop the aircraft in its transfer and will coordinate the aircraft to be towed, at all times safe conditions for the operation must be created.

See the following diagram.

